

P 171949Z

FM NPIC WASHDC

TO RUCSC/SAC OFFUTT AFB OMAHA NEB

RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA

RUCVAA/2D RTS BARKSDALE AFB LA

RUEKDA/DIA WASHDC

RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD

RUEPIA/CIA WASHDC

RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF

RUWGAA/2 AF BARKSDALE AFB LA

BT

SECRET CITE NPIC 7504.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1966 JUN 17 20 24Z

OUT58838

1. CAMERA B 125 WAS USED IN MISSION 8098 FLOWN ON 5 JUNE 1966 PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MINOR EDGE STATIC IS PRESENT ON BOTH FILM EDGES THROUGHOUT THE MISSION. THE LEADING FIDUCIAL ALONG THE OUTBOARD EDGE IS PARTIALLY OBSCURED DUE TO FOREIGN MATTER BUILD-UP. THE TITLING IS BLOCKED ON ALTERNATE FRAMES 10 THROUGH 80 AND 1504 THROUGH 1592. THE VERTICAL DOT INDICATOR IMAGE IS OVEREXPOSED. A MANUFACTURER'S SPLICE IS LOCATED IN FRAME 238 WITH ASSOCIATED INDENTIONS AND STATIC TRACES ON FRAMES 236/237 AND 239.

C. 9L SIDE: MINOR EDGE STATIC IS PRESENT ON THE OUTBOARD EDGE OF THE FILM ON FRAMES 1 THROUGH 300. AN EMULSION SCRATCH AND A MANUFACTURER'S SPLICE IS IN FRAME 1491.

D. BOTH SIDES: SEVERAL FRAMES ARE SMEARED DUE TO VEHICLE MANEUVERS. (EXAMPLES: FRAMES 417, 1013 AND 1209) THE FRAMES ARE TITLED CONSECUTIVELY FROM 000 THROUGH 1655.

20 JUN 1966

DISTRIBUTION

Cy No.	Office	Action
12	FR	
	OS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
34.5	TID	
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy  
Sanitized

--2--

THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 45 PERCENT OF THE MISSION.

GP-1

S E C R E T

-END OF MESSAGE-